



Customer: Eisenbach & Ruhnke Engineering

Workorder No. 0612-00318

Sample: 007 MG-004 STUCCO CAULK  
(Continued)

Parameter	Method	Results	Units	PQL	Tech	Analysis Date/Time	Qual
PCB OIL/SOIL EXTRACTIONS		1.36			ADW	12/29/2006 / 18:16	
Percent Solids	SM 2540G	100	%		TLL	12/29/2006 / 7:20	

Sample: 008 MG-005 WINDOW CAULK  
Collection Date: 12/20/2006  
Matrix: CAULK

Received Date: 12/28/2006 Time: 1:00:00AM

Parameter	Method	Results	Units	PQL	Tech	Analysis Date/Time	Qual
PCB 8082-SOIL/SOLID							
PCB-1016	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1221	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1232	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1242	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1248	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1254	EPA 8082	45200000	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1260	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1262	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
PCB-1268	EPA 8082	ND	ug/Kg	8550000	NAC	01/05/2007 / 16:00	
TCMX (SURROGATE)			%		NAC	01/05/2007 / 16:00	G
DCB (SURROGATE)			%		NAC	01/05/2007 / 16:00	G
PCB OIL/SOIL EXTRACTIONS		1.17			ADW	12/29/2006 / 18:16	
Percent Solids	SM 2540G	100	%		TLL	12/29/2006 / 7:20	

G Surrogate recoveries are not reported due to sample dilution.