



Analytical Report

Creative Environment Solutions Corporation: 06-119.171.7

One Penn Plaza, 7th Floor

New York, NY 10119

Report Date: 5/9/2008


Creative Environment Solutions Corporation: 06-119.171.7


Mailing Information:		Collector's Information:	JMS ID: 089289
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Phone:	(212) 290-6323	Zip:	10119
	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID:	01
Site:	Room 301	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804487

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: 
Michael Lapman
President

Reviewed By: 
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301


Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069290
Name:	Creative Environment Solutions Corporation	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Phone:	(212) 290-6323	Zip:	
	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID:	02
Site:	Room 302	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804488

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
 Michael Lapman
 President

Reviewed By: Sharon Houlahan
 Sharon Houlahan, Director
 State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069291
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Phone:	(212) 290-6323	Zip:	10119
Fax:	(212) 290-6325	Phone:	

Sample's Information:	Sample ID:	03
Site:	Room 303	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804489

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069292
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's information:	Sample ID: 04	
Site: Room 304	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804490
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069293
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	


Sample's Information:	Sample ID: 05	
Site: Room 305	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804491
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



41 Kenosia Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069294
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 06	
Site: Room 306	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804492
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301


Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069295
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 07	
Site: Room 308	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804493
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

 Signature: Michael Lapman
 Michael Lapman
 President

 Reviewed By: Sharon Houlahan
 Sharon Houlahan, Director
 State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069296

Sample's Information:

Sample ID: 08

Site: Room 314
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804494

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman
President

Reviewed By:

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY **Zip:** 10119
Phone: (212) 290-6323 **Fax:** (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY **Zip:**
Phone:

JMS ID: 069297

Sample's Information:

Sample ID: 09

Site: Room 319
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804495

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069298

Sample's Information:

Sample ID: 10

Site: Room 321
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804498

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069299
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Zip:	10119	Zip:	
Phone:	(212) 290-6323	Phone:	
Fax:	(212) 290-6325		

Sample's Information:	Sample ID:	11
Site:	Room 320	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804497

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: <u>Michael Lapman</u>	Reviewed By: <u>Sharon Houlahan</u>
Michael Lapman President	Sharon Houlahan, Director
State #: PH-0218	ELAP #: 11715
	Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporation
 Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Phone: (212) 290-6323

Zip: 10119

Fax: (212) 290-6325

Collector's Information:

JMS ID: 069300

Name: CES

Address of site: 330 Durant Ave
 PS 53R

City: Staten Island

State: NY

Phone:

Zip:

Sample's Information:

Sample ID: 12

Site: Room 323

Preservative: N/A

Temperature:

Matrix: Wipe

Date Collected: 5/3/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 7:00:00 AM

Lab No.: J0804498

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
 President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069301

Sample's Information:

Sample ID: 13

Site: Room 324
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804499

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman
Michael Lapman
President

Reviewed By:

Sharon Houlahan
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301


Creative Environment Solutions Corporation: 06-119.171.7


Mailing Information:		Collector's Information:	JMS ID: 069302
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Zip:	10119	Zip:	
Phone:	(212) 290-6323	Phone:	
Fax:	(212) 290-6325		

Sample's Information:	Sample ID:	14
Site:	Room 329	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804500

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: 
 Michael Lapman
 President

Reviewed By: 
 Sharon Houlahan, Director
 State #: PH-0218 ELAP #: 11715 Ref Lab: 11301


Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069304
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Zip:	10119	Zip:	
Phone:	(212) 290-6323	Fax:	(212) 290-6325
Phone:		Phone:	

Sample's Information:	Sample ID:	15
Site:	Room 334	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804501

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: 

Michael Lapman
President

Reviewed By: 
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's information:	JMS ID: 069305
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 16	
Site: Room 337	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804502
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
 Michael Lapman
 President

Reviewed By: Sharon Houlahan
 Sharon Houlahan, Director
 State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:	Collector's Information:	JMS ID: 069306
Name: Creative Environment Solutions Corporatio	Name: CES	
Address: One Penn Plaza, 7th Floor	Address of site: 330 Durant Ave PS 53R	
City: New York	City: Staten Island	
State: NY Zip: 10119	State: NY Zip:	
Phone: (212) 290-6323 Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 17	
Site: Room 101	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804503
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069307

Sample's Information:

Sample ID: 18

Site: Room 102

Date Collected: 5/3/2008

Date Received: 5/6/2008

Preservative: N/A

Time Collected:

Time Received: 7:00:00 AM

Temperature:

Lab No.: J0804504

Matrix: Wipe

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1282	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman

Michael Lapman
President

Reviewed By: Sharon Houlihan

Sharon Houlihan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069308
Name:	Creative Environment Solutions Corporation	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Zip:	10119	Zip:	
Phone:	(212) 290-6323	Fax:	(212) 290-6325

Sample's Information:	Sample ID:	19
Site:	Room 104	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804505

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069309

Sample's Information:

Sample ID: 20

Site: Room 103
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804506

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:


Michael Lapman
President

Reviewed By:

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301



JMS Environmental Services, Inc.
WATER, SOIL AND AIR ANALYSIS



41 Kenosia Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Phone: (212) 290-6323

Zip: 10119

Fax: (212) 290-6325

Collector's Information:

Name: CES

Address of site: 330 Durant Ave
PS 53R

City: Staten Island

State: NY

Phone:

JMS ID: 069310

Sample's Information:

Sample ID: 21

Site: Room 108

Preservative: N/A

Temperature:

Matrix: Wipe

Date Collected: 5/3/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 7:00:00 AM

Lab No.: J0804507

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218

ELAP #: 11715

Ref Lab: 11301

CONNECTICUT, NEW YORK AND NELAP CERTIFIED

Toll Free 866-JMS-5097 | Corporate Fax 203-798-2408 | Lab Fax 203-798-2107 | www.jmsenvironmental.com

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:		JMS ID: 069311
Name:	Creative Environment Solutions Corporatio	Name:	CES	
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R	
City:	New York	City:	Staten Island	
State:	NY	State:	NY	Zip:
Phone:	(212) 290-6323	Fax:	(212) 290-6325	Phone:

Sample's Information:	Sample ID:	22
Site:	Room 105	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804508

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Zip: 10119

Phone: (212) 290-6323

Fax: (212) 290-6325

Collector's Information:

JMS ID: 069312

Name: CES

Address of site: 330 Durant Ave
PS 53R

City: Staten Island

State: NY

Zip:

Phone:

Sample's Information:

Sample ID: 23

Site: Room 108

Date Collected: 5/3/2008

Date Received: 5/6/2008

Preservative: N/A

Time Collected:

Time Received: 7:00:00 AM

Temperature:

Lab No.: J0804509

Matrix: Wipe

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069313

Sample's Information:

Sample ID: 24

Site: Room 114

Preservative: N/A

Temperature:

Matrix: Wipe

Date Collected: 5/3/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 7:00:00 AM

Lab No.: J0804510

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218

ELAP #: 11715

Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069314

Sample's Information:

Sample ID: 25

Site: Room 120
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804511

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY **Zip:** 10119
Phone: (212) 290-6323 **Fax:** (212) 290-6325

Collector's Information:

JMS ID: 069315

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY **Zip:**
Phone:

Sample's information:

Sample ID: 26

Site: Room 124
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804512

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069316

Sample's Information:

Sample ID: 27

Site: Room 134

Preservative: N/A

Temperature:

Matrix: Wipe

Date Collected: 5/3/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 7:00:00 AM

Lab No.: J0804513

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Phone: (212) 290-6323

Zip: 10119

Fax: (212) 290-6325

Collector's Information:

Name: CES

Address of site: 330 Durant Ave
PS 53R

City: Staten Island

State: NY

Phone:

Zip:

JMS ID: 069317

Sample's Information:

Sample ID: 28

Site: Room 137

Preservative: N/A

Temperature:

Matrix: Wipe

Date Collected: 5/3/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 7:00:00 AM

Lab No.: J0804514

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301



41 Kenosia Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information:

Name: CES
Address of site: 330 Durant Ave
PS 53R

City: Staten Island
State: NY Zip:
Phone:

JMS ID: 069308

Sample's Information:

Sample ID: 19

Site: Room 104
Preservative: N/A
Temperature:
Matrix: Wipe

Date Collected: 5/3/2008
Time Collected:

Date Received: 5/6/2008
Time Received: 7:00:00 AM
Lab No.: J0804505

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:	Collector's Information:	JMS ID: 069309
Name: Creative Environment Solutions Corporatio	Name: CES	
Address: One Penn Plaza, 7th Floor	Address of site: 330 Durant Ave PS 53R	
City: New York	City: Staten Island	
State: NY Zip: 10119	State: NY Zip:	
Phone: (212) 290-6323 Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 20	
Site: Room 103	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804506
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1018	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



41 Kenosla Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:		JMS ID: 069310
Name:	Creative Environment Solutions Corporatio	Name:	GES	
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 63R	
City:	New York	City:	Staten Island	
State:	NY	State:	NY	Zip:
Phone:	(212) 290-6323	Fax:	(212) 290-6325	Phone:

Sample's Information:	Sample ID:	21
Site:	Room 108	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804507

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069311
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Zip:	10119	Zip:	
Phone:	(212) 290-6323	Fax:	(212) 290-6325
Phone:		Phone:	


Sample's Information:	Sample ID:	22
Site:	Room 105	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Collected:
Matrix:	Wipe	Time Received: 7:00:00 AM
		Lab No.: J0804508

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1280	<0.1 ug/wipe	E8082
05/08/08	PCB-1282	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

JMS Environmental Services, Inc. WATER, SOIL AND AIR ANALYSIS  41 Kenosia Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:		JMS ID: 069312
Name: Creative Environment Solutions Corporatio		Name: CES		
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave PS 53R		
City: New York		City: Staten Island		
State: NY	Zip: 10119	State: NY	Zip:	
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:		

Sample's Information:	Sample ID: 23	
Site: Room 108	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804509
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

CONNECTICUT, NEW YORK AND NELAP CERTIFIED

Toll Free 866-JMS-5087 | Corporate Fax 203-798-2408 | Lab Fax 203-798-2107 | www.jmsenvironmental.com



41 Kenosia Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:
Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York
State: NY Zip: 10119
Phone: (212) 290-6323 Fax: (212) 290-6325

Collector's Information: JMS ID: 069313
Name: CES
Address of site: 330 Durant Ave
PS 53R
City: Staten Island
State: NY Zip:
Phone:

Sample's Information: Sample ID: 24

Site: Room 114 Date Collected: 5/3/2008 Date Received: 5/6/2008
Preservative: N/A Time Collected: Time Received: 7:00:00 AM
Temperature: Lab No.: J0804510
Matrix: Wipe

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



41 Kenosla Avenue
Danbury, Connecticut 06810 | Telephone 203-798-2229

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:		JMS ID: 069314
Name:	Creative Environment Solutions Corporatio	Name:	CES	
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R	
City:	New York	City:	Staten Island	
State:	NY	State:	NY	Zip:
Phone:	(212) 290-6323	Fax:	(212) 290-6325	Phone:

Sample's Information:	Sample ID:	25
Site:	Room 120	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804511

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715



Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:	Collector's Information:	JMS ID: 069315
Name: Creative Environment Solutions Corporatio	Name: CES	
Address: One Penn Plaza, 7th Floor	Address of site: 330 Durant Ave PS 53R	
City: New York	City: Staten Island	
State: NY Zip: 10119	State: NY Zip:	
Phone: (212) 290-6323 Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 26	
Site: Room 124	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804512
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:

Name: Creative Environment Solutions Corporatio
Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Zip: 10119

Phone: (212) 290-6323

Fax: (212) 290-6325

Collector's Information:

JMS ID: 069316

Name: CES

Address of site: 330 Durant Ave
PS 53R

City: Staten Island

State: NY

Zip:

Phone:

Sample's Information:

Sample ID: 27

Site: Room 134

Date Collected: 5/3/2008

Date Received: 5/6/2008

Preservative: N/A

Time Collected:

Time Received: 7:00:00 AM

Temperature:

Lab No.: J0804513

Matrix: Wipe

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature:

Michael Lapman

Michael Lapman
President

Reviewed By:

Sharon Houlahan

Sharon Houlahan, Director

State #: PH-0218 **ELAP #:** 11716

Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069317
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID: 28	
Site: Room 137	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804514
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
 Michael Lapman
 President

Reviewed By: Sharon Houlahan
 Sharon Houlahan, Director
 State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069318
Name:	Creative Environment Solutions Corporatio	Name:	CES
Address:	One Penn Plaza, 7th Floor	Address of site:	330 Durant Ave PS 53R
City:	New York	City:	Staten Island
State:	NY	State:	NY
Phone:	(212) 290-6323	Zip:	
	Fax: (212) 290-6325	Phone:	

Sample's Information:	Sample ID:	29
Site:	Field Blank 1	Date Collected: 5/3/2008
Preservative:	N/A	Date Received: 5/6/2008
Temperature:		Time Received: 7:00:00 AM
Matrix:	Wipe	Lab No.: J0804515

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: Michael Lapman
Michael Lapman
President

Reviewed By: Sharon Houlahan
Sharon Houlahan, Director
Ref Lab: 11301

State #: PH-0218 ELAP #: 11715

Creative Environment Solutions Corporation: 06-119.171.7

Mailing Information:		Collector's Information:	JMS ID: 069319
Name: Creative Environment Solutions Corporatio		Name: CES	
Address: One Penn Plaza, 7th Floor		Address of site: 330 Durant Ave	
		PS 53R	
City: New York		City: Staten Island	
State: NY	Zip: 10119	State: NY	Zip:
Phone: (212) 290-6323	Fax: (212) 290-6325	Phone:	

Sample's Information: **Sample ID:** 30

Site: Field Blank 2	Date Collected: 5/3/2008	Date Received: 5/6/2008
Preservative: N/A	Time Collected:	Time Received: 7:00:00 AM
Temperature:		Lab No.: J0804516
Matrix: Wipe		

Date Analyzed	Test Name	Result	Method
05/08/08	PCB-1016	<0.1 ug/wipe	E8082
05/08/08	PCB-1221	<0.1 ug/wipe	E8082
05/08/08	PCB-1232	<0.1 ug/wipe	E8082
05/08/08	PCB-1242	<0.1 ug/wipe	E8082
05/08/08	PCB-1248	<0.1 ug/wipe	E8082
05/08/08	PCB-1254	<0.1 ug/wipe	E8082
05/08/08	PCB-1260	<0.1 ug/wipe	E8082
05/08/08	PCB-1262	<0.1 ug/wipe	E8082
05/08/08	PCB-1268	<0.1 ug/wipe	E8082

ug/wipe = ug/Wipe 10x10cm

Signature: <u>Michael Lapman</u>	Reviewed By: <u>Sharon Houlahan</u>
Michael Lapman President	Sharon Houlahan, Director
State #: PH-0218	ELAP #: 11715 Ref Lab: 11301

Round 3 / Phase A
 05/03/08 - ~~Wipe~~
 - Wipe



Creative Environment Solutions Corporation

One Penn Plaza • 7th Floor • New York • NY 10119
 (212) 290 - 6323 • FAX (212) 290 - 6325

SAMPLING CHAIN-OF-CUSTODY FORM PAGE (1 OF 3)

Date Collected: 05/03/08	Project Name: SCA PCB Sampling @ PS 53R	Client: NYC SCA
Collected by: CES	Location: 330 Durant Avenue, Staten Island, NY 10301	LLW#:
		SCA Job#:
		CES Project/Task:06-119.171.7

Task / Activity: Inspection, Repair/ Interim Control,
 Construction/Alteration/Demolition, Other: _____

Matrix: S = SOIL; L = LIQUID; A = AIR; SL = SLUDGE; W = WIPE; P = PAINT CHIPS; B = BULK MATERIAL

Laboratory: Adirondack Env. ; ELAP No. 10709 Analysis Requested: As Indicated
 York Labs ; ELAP No. 10854
 JMS ; ELAP No. 11715

Sample ID	Matrix	Sample Location / Description	Analysis Requested/Results:				
			Asbestos (PLM)	PCB EPA 9062	Mercury	Pb,Cr,Cd,As	SVOC-4 Phthalates
01	W	3' From 3rd Window on 9x9 Floor Tile - Room# 301		X			
02		3' From 3rd Window on 9x9 Floor Tile - Room# 302		X			
03		3' From 2nd Window on 9x9 Floor Tile - Room# 303		X			
04		2' From 5th Window on 9x9 Floor Tile - Room# 304		X			
05		3' From 4th Window on 9x9 Floor Tile - Room# 305		X			
06		3' From 9th Window on Limestone Tile - Room# 306		X			
07		2' From 2nd Window on 9x9 Floor Tile - Room# 308		X			
08		3' From 2nd Window on 9x9 Floor Tile - Room# 314		X			
09		3' From 2nd Window on 9x9 Floor Tile - Room# 319		X			
10		2' From 1st Window on 9x9 Floor Tile - Room# 321		X			
11		3' From 3rd Window on 9x9 Floor Tile - Room# 320		X			
12		2' From 6th Window on 9x9 Floor Tile - Room# 323		X			
13	W	2' From 6th Window on 9x9 Floor Tile - Room# 324		X			

Turn-Around-Time: Immediate, 4 Hr, 24 Hr, 48 Hr, 72 Hr Results to: X Fax: (212) 290-6325
 3-5 Days, Standard, Other: by 05/04/08 X E-mail: ceslubresults@aol.com

Site			Laboratory					
Relinquished By	Date	Time	Received By	Date	Time	Analyzed By	Date	Time
Name (Print)	05/05/08	11:05	Name (Print)	5/6/08	7:00	Name (Print)	5/6/08	1:00
Signature			Signature			Signature		



Creative Environment Solutions Corporation
 One Penn Plaza • 7th Floor • New York • NY 10119
 (212) 290 - 6323 • FAX (212) 290 - 6325

SAMPLING CHAIN-OF-CUSTODY FORM PAGE (2 OF 3)

Date Collected: <i>05/03/08</i>	Project Name: SCA PCB Sampling @ PS 53R	Client: NYC SCA
Collected by: <i>CES</i>	Location: 330 Durant Avenue, Staten Island, NY 10301	LLW#:
		SCA Job#:
		CES Project/Task:06-119.171.7

Task / Activity: Inspection, Repair/ Interim Control,
 Construction/Alteration/Demolition, Other: _____

Matrix: s = SOIL; L = LIQUID; A = AIR; SL = SLUDGE; W = WIPE; P = PAINT CHIPS; B = BULK MATERIAL

Laboratory: Adirondack Env. ; ELAP No. 10709 Analysis Requested: As Indicated
 York Labs ; ELAP No. 10854
 JMS ; ELAP No. 11715

Sample ID	Matrix	Sample Location / Description	Analysis Requested/Results:				
			Asbestos (PLM)	PCB EPA 8082	Mercury	Pb, Cr, Cd, As	SVOC-4 Phthalates
14	W	1' From 7th Window on 9x9 Floor Tile - Room# 3 29		X			
15		2' From 6th window on 9x9 Floor Tile - Room# 3 34		X			
16		3' From 3rd window on 9x9 Floor Tile - Room# 337		X			
17		3' From 3rd window on 9x9 Floor Tile - Room# 101		X			
18		2' From 4th window on 9x9 Floor Tile - Room# 102		X			
19		2' From 4th window on Lilonium Tile - Room# 104		X			
20		2' From 5th window on 9x9 Floor Tile - Room# 103		X			
21		3' From 1st window on Lilonium Tile - Room# 106		X			
22		3' From 3rd window on 9x9 Floor Tile - Room# 105		X			
23		3' From 1st window on Lilonium Tile - Room# 108		X			
24		2' From 4th window on Lilonium Tile - Room# 114		X			
25		3' From 6th window on 9x9 Floor Tile - Room# 120		X			
26	W	3' From 4th window on 9x9 Floor Tile - Room# 124		X			

Turn-Around-Time: Immediate, 4 Hr, 24 Hr, 48 Hr, 72 Hr Results to: X Fax: (212) 290-6325
 3-5 Days, Standard, & Other: by 05/09/08 X E-mail: ceslubresults@aol.com

Site			Laboratory					
Relinquished By	Date	Time	Received By	Date	Time	Analyzed By	Date	Time
Name (Print)	<i>05/05/08</i>	<i>11:05</i>	Name (Print)			Name (Print)		
<i>V. Linares</i>			Signature			<i>Joyce Waters</i>		
Signature				Signature			Signature	
						<i>Joyce Waters</i>		



Creative Environment Solutions Corporation
 One Penn Plaza • 7th Floor • New York • NY 10119
 (212) 290 - 6323 • FAX (212) 290 - 6325

SAMPLING CHAIN-OF-CUSTODY FORM PAGE (3 OF 3)

Date Collected: <u>05/03/08</u>	Project Name: SCA PCB Sampling @ PS 53R	Client: NYC SCA
Collected by: <u>CES</u>	Location: 330 Durant Avenue, Staten Island, NY 10301	LLW#:
		SCA Job#:
		CES Project/Task: 06-119.171.7

Task / Activity: Inspection, Repair/ Interim Control,
 Construction/Alteration/Demolition, Other: _____

Matrix: S = SOIL; L = LIQUID; A = AIR; SL = SLUDGE; W = WIPE; P = PAINT CHIPS; B = BULK MATERIAL

Laboratory: Adirondack Env. ELAP No. 10709 Analysis Requested: As Indicated
 York Labs ELAP No. 10854
 JMS ELAP No. 11715

Sample ID	Matrix	Sample Location / Description	Analysis Requested/Results:				
			Asbestos (PLM)	PCB EPA 8062	Mercury	Pb, Cr, Cd, As	SVOC - 4 Pthalates
27	W	2' From 6th Window on 9x9 Floor Tile - Room #134		X			
28	W	4' From Window on 9x9 Floor Tile - Room #137		X			
29		Field Blank #1		X			
30		Field Blank #2		X			

Turn-Around-Time: Immediate, 4 Hr, 24 Hr, 48 Hr, 72 Hr. Results to: X Fax: (212) 290-6325
 3-5 Days, Standard, Other: by 05/07/08 X E-mail: ceslubresults@aol.com

Site			Laboratory					
Relinquished By	Date	Time	Received By	Date	Time	Analyzed By	Date	Time
Name (Print)	<u>05/05/08</u>	<u>11:05</u>	Name (Print)			Name (Print)		
Signature			Signature			Signature		
						<u>Joyce Waters</u>		
						Signature		
						<u>Joyce Waters</u>		