

# Analytical Report

**Creative Environment Solutions Corporation: 06-119.171.7**  
One Penn Plaza, 7th Floor  
New York, NY 10119

Report Date: 5/8/2008

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**City:** New York  
**State:** NY **Zip:** 10119  
**Phone:** (212) 290-6323 **Fax:** (212) 290-6325

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**City:** Staten Island  
**State:** NY **Zip:**  
**Phone:**

**JMS ID:** 069343

**Sample's Information:**

**Sample ID:** 01

**Site:** Lawn N. Side  
**Preservative:** N/A  
**Temperature:** <4  
**Matrix:** Soil

**Date Collected:** 5/5/2008  
**Time Collected:**

**Date Received:** 5/6/2008  
**Time Received:** 4:40:00 PM  
**Lab No.:** J0804581

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	<50 ppb	SW 8082
05/07/08	PCB-1260	656 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

Signature:

*Michael Lapman*

Michael Lapman  
President

Reviewed By:

*Sharon Houlihan*

Sharon Houlihan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**JMS ID:** 069344

**City:** New York

**State:** NY

**Phone:** (212) 290-6323

**Zip:** 10119

**Fax:** (212) 290-6325

**City:** Staten Island

**State:** NY

**Phone:**

**Zip:**

**Sample's Information:**

**Sample ID:** 02

**Site:** Lawn N. Side

**Preservative:** N/A

**Temperature:** <4

**Matrix:** Soil

**Date Collected:** 5/5/2008

**Time Collected:**

**Date Received:** 5/6/2008

**Time Received:** 4:40:00 PM

**Lab No.:** J0804582

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	<50 ppb	SW 8082
05/07/08	PCB-1260	219 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

**Signature:**

*Michael Lapman*

Michael Lapman

President

**Reviewed By:**

*Sharon Houlahan*

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301



**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio

**Address:** One Penn Plaza, 7th Floor

**City:** New York

**State:** NY

**Phone:** (212) 290-6323

**Zip:** 10119

**Fax:** (212) 290-6325

**Collector's Information:**

**Name:** CES

**Address of site:** 330 Durant Ave

**City:** Staten Island

**State:** NY

**Phone:**

**Zip:**

**JMS ID:** 069345

**Sample's Information:**

**Sample ID:** 03

**Site:** Lawn E. Side

**Preservative:** N/A

**Temperature:** <4

**Matrix:** Soil

**Date Collected:** 5/5/2008

**Time Collected:**

**Date Received:** 5/6/2008

**Time Received:** 4:40:00 PM

**Lab No.:** J0804583

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	3710 ppb	SW 8082
05/07/08	PCB-1260	3883 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

Signature:

*Michael Lapman*

Michael Lapman

President

Reviewed By:

*Sharon Houlahan*

Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

Name: Creative Environment Solutions Corporatio

Address: One Penn Plaza, 7th Floor

City: New York

State: NY

Phone: (212) 290-6323

Zip: 10119

Fax: (212) 290-6325

**Collector's Information:**

Name: CES

Address of site: 330 Durant Ave

City: Staten Island

State: NY

Phone:

Zip:

JMS ID: 069346

**Sample's Information:**

Sample ID: 04

Site: Lawn E. Side

Preservative: N/A

Temperature: <4

Matrix: Soil

Date Collected: 5/5/2008

Time Collected:

Date Received: 5/6/2008

Time Received: 4:40:00 PM

Lab No.: J0804584

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	3504 ppb	SW 8082
05/07/08	PCB-1260	3902 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

Signature: Michael Lapman  
Michael Lapman  
President

Reviewed By: Sharon Houlahan  
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715

Ref Lab: 11301



**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**JMS ID:** 069347

**City:** New York  
**State:** NY      **Zip:** 10119  
**Phone:** (212) 290-6323      **Fax:** (212) 290-6325

**City:** Staten Island  
**State:** NY      **Zip:**  
**Phone:**

**Sample's Information:**

**Sample ID:** 05

**Site:** Lawn W. Side

**Date Collected:** 5/5/2008

**Date Received:** 5/6/2008

**Preservative:** N/A

**Time Collected:**

**Time Received:** 4:40:00 PM

**Temperature:** <4

**Lab No.:** J0804585

**Matrix:** Soil

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	1233 ppb	SW 8082
05/07/08	PCB-1260	1684 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

**Signature:** Michael Lapman  
Michael Lapman  
President

**Reviewed By:** Sharon Houlahan  
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**JMS ID:** 069348

**City:** New York

**State:** NY

**Phone:** (212) 290-6323

**Zip:** 10119

**Fax:** (212) 290-6325

**City:** Staten Island

**State:** NY

**Phone:**

**Zip:**

**Sample's Information:**

**Sample ID:** 06

**Site:** Lawn W. Side

**Preservative:** N/A

**Temperature:** <4

**Matrix:** Soil

**Date Collected:** 5/5/2008

**Time Collected:**

**Date Received:** 5/6/2008

**Time Received:** 4:40:00 PM

**Lab No.:** J0804586

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	946 ppb	SW 8082
05/07/08	PCB-1260	1160 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

**Signature:** Michael Lapman  
Michael Lapman  
President

**Reviewed By:** Sharon Houlahan  
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**JMS ID:** 069349

**City:** New York  
**State:** NY      **Zip:** 10119  
**Phone:** (212) 290-6323      **Fax:** (212) 290-6325

**City:** Staten Island  
**State:** NY      **Zip:**  
**Phone:**

**Sample's Information:**

**Sample ID:** 07

**Site:** Lawn S. Side  
**Preservative:** N/A  
**Temperature:** <4  
**Matrix:** Soil

**Date Collected:** 5/5/2008  
**Time Collected:**

**Date Received:** 5/6/2008  
**Time Received:** 4:40:00 PM  
**Lab No.:** J0804587

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	<50 ppb	SW 8082
05/07/08	PCB-1260	60.2 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

**Signature:** Michael Lapman  
Michael Lapman  
President

**Reviewed By:** Sharon Houlahan  
Sharon Houlahan, Director

State #: PH-0218 ELAP #: 11715 Ref Lab: 11301

**Creative Environment Solutions Corporation: 06-119.171.7**

**Mailing Information:**

**Name:** Creative Environment Solutions Corporatio  
**Address:** One Penn Plaza, 7th Floor

**Collector's Information:**

**Name:** CES  
**Address of site:** 330 Durant Ave

**JMS ID:** 069350

**City:** New York

**State:** NY

**Phone:** (212) 290-6323

**Zip:** 10119

**Fax:** (212) 290-6325

**City:** Staten Island

**State:** NY

**Phone:**

**Zip:**

**Sample's information:**

**Sample ID:** 08

**Site:** Lawn S. Side

**Preservative:** N/A

**Temperature:** <4

**Matrix:** Soil

**Date Collected:** 5/5/2008

**Time Collected:**

**Date Received:** 5/6/2008

**Time Received:** 4:40:00 PM

**Lab No.:** J0804588

Date Analyzed	Test Name	Result	Method
05/07/08	PCB-1016	<50 ppb	SW 8082
05/07/08	PCB-1221	<50 ppb	SW 8082
05/07/08	PCB-1232	<50 ppb	SW 8082
05/07/08	PCB-1242	<50 ppb	SW 8082
05/07/08	PCB-1248	<50 ppb	SW 8082
05/07/08	PCB-1254	<50 ppb	SW 8082
05/07/08	PCB-1260	<50 ppb	SW 8082
05/07/08	PCB-1262	<50 ppb	SW 8082
05/07/08	PCB-1268	<50 ppb	SW 8082

ppb = parts per billion

**Signature:** Michael Lapman

Michael Lapman

President

**Reviewed By:** Sharon Houlahan

Sharon Houlahan, Director

~~State #: PH-0218~~ ~~ELAP #: 11715~~

~~Ref Lab: 11301~~



# Creative Environment Solutions Corporation

One Penn Plaza • 7<sup>th</sup> Floor • New York • NY 10119

(212) 290 - 6323 • FAX (212) 290 - 6325

## SAMPLING CHAIN-OF-CUSTODY FORM

PAGE (1) OF (1)

Date Collected: 05/05/08	Project Name: SCA PCB SAMPLING	Client: NYC SCA
Collected by: Giorgi Kabanashvili	Location: 330 Durant Avenue, Staten Island, NY 10308	LLW#:
		SCA Job#:
		CES Project/Task: 06-119.171.7

Task / Activity:  Inspection,  Repair/ Interim Control,  
 Construction/Alteration/Demolition,  Other: \_\_\_\_\_

Matrix:  SOIL; L = LIQUID; A = AIR; SL = SLUDGE; W = WIPE; P = PAINT CHIPS; B = BULK MATERIAL

Laboratory: X JMS ELAP No. 11715 Analysis Requested: As Indicated

Sample ID	Matrix	Sample Location / Description	Analysis Requested/Results:				
			Asbestos (PLM)	PCB EPA 8082	Mercury	Pb, Cr, Cd, As	SVOC - 4 Phthalates
01	S	Lawn, North Side Of Building, Durant Av. Side 2"-6"		X			J0804581
02	S	Lawn, North Side Of Building, Durant Av. Side 6"-12"		X			J0804582
03	S	Lawn, East Side Of Building, RedGrave Av Side 2"-6"		X			J0804583
04	S	Lawn, East Side Of Building, RedGrave Av Side 6"-12"		X			J0804584
05	S	Lawn, West Side Of Building, Ainsworth Av Side 2"-6"		X			J0804585
06	S	Lawn, West Side Of Building, Ainsworth Av Side 6"-12"		X			J0804586
07	S	Lawn, South Side Of Building, Greencroft Av Side 2"-6"		X			J0804587
08	S	Lawn, South Side Of Building, Greencroft Av Side 6"-12"		X			J0804588

Turn-Around-Time:  Immediate,  4 Hr,  24 Hr,  48 Hr,  72 Hr Results to: X Fax: (212) 290-6325  
 3-5 Days,  Standard,  Other X E-mail: ceslubresults@aol.com

Special Instructions: \_\_\_\_\_  Other: \_\_\_\_\_

Site			Laboratory					
Relinquished By	Date	Time	Received By	Date	Time	Analyzed By	Date	Time
Name (Print)	05/06/08		Name (Print)	5/6/08	4:40 PM	Name (Print)	5/7/08	
Giorgi Kabanashvili			Jill CRAIG			Joyce Waters		2:00
Signature			Signature			Signature		
<i>G. Kabanashvili</i>			<i>Jill Craig</i>			<i>Joyce Waters</i>		